





41. Ponding near roof perimeter .



42. Weld spatter on roof



43. Peeled coating on roof.



44. Roof.





45. Roof manhole. Note corrosion on cover.




46. Roof manhole and interior ladder. Note corrosion.






47. Roof vent. Note corrosion.



48. Roof vent screening.





49. Roof and roof support structure.



50. Roof and roof support structure.



51. Corrosion and metal loss at rafter-to-clip connection.




52. Corrosion and metal loss at rafter-to-clip connection.







53. Corrosion and metal loss on roof rafter.



54. Corrosion and metal loss on purlin.



55. Center hub, center column, and roof rafters.



56. Roof support structure. Note corrosion and metal loss.





57. Corrosion on shell.



58. Corrosion on shell.



59. Area on shell damaged from exterior welding.



60. Center column.